

SAMPLE FOOT DRAWING


Pendragon Boot Company

step 1

Draw around the foot with ballpoint pen at 90° to the page to make outer line .

step 2

Draw around the foot with ballpoint pen at 45° to the page to make inside line.



22cm

23cm

Step 3

Measure all the way around the foot with a tape measure at the toes, ball of foot and instep. Mark points measured on foot drawing. Write measurements clearly next to points measured.

25cm

Step 4

For boots - measure around heel to ankle at the widest point.

